



**5 to 15-Year Warranty Extension and 100+ MPH Wind Rider  
Hurricane Back Wrap Compression Board Warranty Upgrade  
Over An Existing 2001 Co. Wind Vented Roof Assembly**

**Summary Specification**

1. Remove any existing deteriorated perimeter and penetration compression boards and restore air seals where necessary.
- 2.. Upgrade the total roof assembly by installing Hurricane **Back Wrap Compression Board** air seal details over the existing perimeter and penetration air seal compression boards.  
Install a new 1/2" plywood or OSB wafer board APA-approved exterior sheeting board over the existing 2001 Co. warranted roof perimeter and penetrations and recover the new sheeting surface with reinforced field membrane.

**Repair and Maintenance Hurricane Back Wrap Compression Air Seal Details**

Copies attached.

(See double compression board details Repair to Vertical Wall Angle Change Termination).

**NOTE:** 2001 Co. requires reinforced membrane only for this warranty upgrade.



3. Re-flash the perimeter, penetrations and roof top appendages to 2001 Co. flashing details.
4. Check all existing vertical wall exposed termination bars with a cotter pin puller tool (seam probe) for sound attachment. Re-terminate with additional 2001 Co. termination bars below any areas where deteriorated finish flashing termination bars are not holding in the vertical wall. Use a larger or longer fastener.
5. Cover tape over all field seams in ponding water with 7" cover tape: Ponding water is defined as water remaining 48 hours after a rain storm.
6. Vertical wall waterproofing:  
On adjoining higher walls, and parapets flashed above base flashings. 2001 Co. recommends our **Wind Vented Reinforced Membrane Vertical Wall Waterproofing Technique** over paints coatings, vertical siding, stucco, silicone, silaxane and other wall waterproofing options, see detail copies attached.
7. For a **5 to 15-year 2001 Co. Warranty Extension**, and a **100 mph or higher Wind Rider**, schedule a roof inspection by a 2001 Co. field technician for this warranty upgrade maintenance compliance.

*Mailing Address: P.O. Box 2557, Waterbury, CT 06723-2557*  
*Shipping Address: 325 Thomaston Avenue, Waterbury, CT 06702*  
Tel: (203) 575-9220 ● Fax: (203) 573-0781 ● [www.2001Company.com](http://www.2001Company.com)