



January 2, 2015

## 2001 Co. Wind Vented Wall Systems – Introduction

Sometimes the best roof does not stop all leaks when the existing exposed parapet walls absorb moisture. 2001 Co. has a wind vented system that will dry out a wall that has been saturated from aging cementous components or has moisture accumulated from from interior heat loss. 2001 Co. can dry out your roof and your parapet walls with the 2001 Wind Vented Wall Systems.